
### Historic, archived document

Do not assume content reflects current scientific knowledge, policies, or practices.





## HINTS

UNITED STATES DEPARTMENT OF AGRICULTURE, FOREST SERVICE WASHINGTON, D. C.

June 25, 1938.

Vol. 4

No. 12

OIL FILTER INSTALLATION

Harry G. Houlding, Camp Walhalla, F-23
Manistee National Forest


Having installed oil filters on the 1935 Chevrolet stake trucks as an added improvement, by fastening them to the dash board, considerable trouble was experienced with the fittings becoming loose and leaking.

The vibration of the cab in opposition to the motor movements caused the pipe to wear the fitting, resulting in leaks and excessive repair.

The difficulty was overcome by installing the regular oil filter clamp on the rear half of the intake manifold. This was done by drilling  $1/4^n$  holes through the manifold pipe, tapping them out with  $5/16^n$  threads, and using cap screws to hold the clamp in place.


This eliminated the necessity of all further repair and overcame the troubles previously experienced.

#### OIL FILTER INSTALLATION




MANISTEE - F 23 H.G.H.

#### CONSTRUCTION HINT



#### SIDE VIEW




#### BOTTOM VIEW

STONE DOLLY -- TO HANDLE STONE FOR BRIDGES -- IN LOADING STONE ON TRUCKS AND MOVING STONE AT BRIDGE SITE.

#### STONE DOLLY

DESIGNED: O.N. MILLER JR.
PENNA. C.C.C. - S 87
REGION 7



# STANDARD OIL COMPANY OF NEW JERSEY GOVERNMENT SERVICE W/SHIIGTON, D. C.

Excessive wear and eventual failure of the differential gears in the equipment listed herein will occur if not lubricated with products having load carrying characteristics suitable for hypoid or over-loaded spiral-bevel gears.

		and a like
1934	1936 Cont'd.	1938 Cont'd.
Auburn	Ford	LaSalle
Chrysler (1)	Graham	Graham
Duesenberg	Hudson	Lincoln Zephyr
Ford	Hupmobile	Nash
Graham	LaFayette	Oldsmobile
Hudson	LaSalle	Packard
Hupmobile (4)	Nash	Pierce-Arrow
LaFayette	Oldsmobile 6, 8	Plymouth
Marmon 16	Packard	Studebaker
Nash	Pierce-Arrow	Terraplane
Oldsmobile 8	Plymouth	
Packard	Stutz	
Pierce-Arrow	Terraplane	
Plymouth		
Stutz	1937	
Terraplane	Buick 40, 60	
	Cadillac	
<u>1935</u>	Chevrolet	
Auburn	Chrysler (1)	
Chrysler (1)	DeSoto (2)	
DeSoto (2)	Dodge	
Duesenberg	Duesenberg	
Ford	Ford	
Graham	Graham	
Hudson	Hudson	NOMES -
Hupmobile	LaSalle	NOTES:
LaFayette	Nash	(7) Through Adv. 67 1. 3 -
Nash	Oldsmobile 6, 8	(1) Except Airflow models,
Oldsmobile 6, 8	Packard	Imperials and 135
Packard	Pierce-Arrow	Custom Imperials.
Pierce-Arrow	Plymouth	(2) Theorem 12/ 14/07
Plymouth	Studebaker	(2) Except 34 Airflow,
Stutz	Terraplane	all '35 and some '36
Terraplane		Airstreams
·	1938	(2) Company James 2 2 2 2 1
<u>1936</u>	Buick	(3) Some sedans only after
Auburn	Cadillac	serial No. 4,128,318.
Buick	Chevrolet	//) There are 1 7 /75
Cadillac	Chrysler	(4) Except model 417
Chrysler (1)	DeSoto	
DeSoto (2)	Dodge	
Dad. (2)	T 1	

Ford

Hudson Hupmobile

Dodge (3)

Duesenberg

## TRUCK AND COMMERCIAL MODELS REQUIRING HYPOID OR EXTREME PRESSURE LUBRICANTS

Jiamond T DR Series

Dodge 37 MC
37 MD, ME, NF
37 MF, MG
36 LF and LH Series
34-35 KH-30, K-30 and
K-40 Series
Prev. All

Chevrolet -

Duplex 35-37 S, SC, SAC, K,
SAK (Worm)
Prev. Worm

Fageol -Waukesha 6RB

Flxible -37 Chevrolet 35 Buick - 90

Ford - 37 - 60, 85 32-36 - V8 32-34 - 4 F.W.D. HS, T 26
M7
And others

Mack - Hypoid models

Menominee - 35-36, 1-15 35-36, Others

Meteor -37 LaSalle and Cadillac 36 LaSalle and Cadillac

Oshkosh - All

Schacht - 36-37 All

Studebaker - 37 - J5

Terraplane -37 - All Prev. All

#### SIGNS OF SAFETY

Don't Rush - It is Better to Kill Time than People: